BRUHAT BANGALORE MAHANGARA PALIKE

Inspection Report

1	Name Of Work:	Providing and laying HDPE water line in HMT Layout Block 2 in JP Park ward 17
2	Administration Approval & Date	JC/RRN/AS/2249/2013-14 Dtd: 17.09.2013
3	Technical Sanction Estimate No. & Date	CE/RRN/TS/296/2013-14 Dtd: 18.09.2013
4	Estimate Amount	49,90,000/-
5	Job Code No.	017-14-000017
6	P-Code	P-2201
7	Agreement No and Date:	EE/RRND/Agmt/219/13-14 Dtd: 05.02.2014
8	Work order Number & Date	EE/RRND/WO/219/13-14 Dtd: 05.02.2014
9	Contract Amount as per Agreement	Rs. 53,38,200/-
10	Bill Amount	Rs. 47,39,564=41
11	B.R No. & Date	319/14-15 Dtd: 31.07.2014
12	Agency	L Nithyananda Prabhu
13	M.B. Number & Page No. of Measurement records	85/12-13 Page No 8480 to 8487
14	Date of Inspection	08.09.2017
15	Enclosures	4 Number of photos taken during inspection
16	I have Inspected the above site location along with the Conserned person, as per EE(RRND) Letter No EE/RRN/PR/414/A/17-18 Dated 1-9-2017. It is observed that most of the Items indicated in the Xerox Copy of MB/XL sheets are not susceptible for measurements, as the nature of work is Laying HDPE water Line, as such the photos taken during the execution of work have been scrutinised and Inspected, it appears that the above work has been done. The Items which are susceptible for measurements have been checked and found to be satisfactory. This has a reference to the NOC Issued by Lokayukta vide Letter No LOK/INV(J) CT/ Crime 60/2014 Dated 1-8-2017.	

8/9/2017

(R. Sathyanarayana)
Inspection Report Officer.

R. SATHYANARAYANA
INSPECTION OFFICER

EE (RRN) Division, RR Nagara Zone.

Scanned by CamScanner